Room	Walls	Floor	Ceiling	Door/Ironmongery	Window	Fixtures/Fittings	Notes
B57& B58 Exist.	Masonry walls.	Concrete floor Concrete finish	Concrete (Under Foot-path)	Flush Fire door. Gloss paint finishes Ironmongery- old satin SS door handle of no historic value. Door closers	Crittall Windows and Metal Burglary proofing	Skirting – None	Redundant electrical services and discontinued metal trunking remain on walls.
B57& B58 Prop.	Strip M&E services Repair cracks and stop in holes. Make good walls, Render walls as spec <b>M20</b> Decorate as spec <b>M60</b> .	Damp treatment if required. Damp proof Paint as spec <b>M50</b> .	Strip M&E Services Skim finish <b>M20</b> Prepare and decorate as spec <b>M60</b> .	Retain doorframe, lining architrave. Provide new 4- panelled door spec L20 complete with Ironmongery P21.	Prepare and redecorate cills Decorate existing Crittall windows and secondary glazing as spec M60		Strip out plant and mechanical services. Strip out electrical services and install new M&E Services. Refer to M&E spec.

ROOM B57 & 58 IMAGES

Fig. B57/58.1– View 1	Fig. B57/58.1– View 2	Fig. B57/58.1– View 3	Fig. B57/58.1– View 4	

Room	Walls	Floor	Ceiling	Door/Ironmongery	Window	Fixtures/Fittings	Notes
G1	Masonry/Lath &	Timber floor	Lath & plaster.	Old 4 panelled fire door	Sash window. Georgian	Skirting – 230mm High	Redundant power
Exist.	Plaster emulsion paint on Walls paper. <b>W1</b> - large service trunking at high-level length of room. Heating pipes at low level.	Carpet finish	Poor finish. Appear crumbling. Wall papered and painted in white emulsion. Decorative plaster coving	Upper Georgian wire - glazed panes (longer). Several coats Gloss paint finishes. Ironmongery- old satin SS door handle of no historic importance.	glazing bars. Architrave Timber window cills in poor condition.	Ogee painted in white gloss. 100mm pencil round on <b>W4</b> white. Stone Fireplace boarded up and air vent above. Wall shelving.	sockets and discontinued metal trunking remain on walls. Floor Standing Cast Iron Radiator. Stone Fire place.
G1 Prop.	Strip out M&E services. Strip walls of wallpaper. Repair cracks and Make good walls, Skim <b>M20</b> Decorate as spec <b>M60</b> .	Remove exist. Carpet, Rid the floor of glue, staples etc Prepare floor and install new carpet flooring as spec <b>M50</b> .	Strip ceiling of wallpaper. Allow for the installation of new services. Skim finish <b>M20</b> Prepare and decorate as spec <b>M60</b> .	Retain doorframe, lining architrave. Provide new matching 4-panelled fire door spec L20 complete with Ironmongery P21.	. And decorate existing window and cill as spec M60.	Remove shelving and noggin. Repair cracks and Make good walls. Retain Ogee skirting on W1, W2 & W3.Replace skirting on W4 with matching Ogee skirting. Decorate as spec. M60	Allow for dado trunking. Provide nev steel radiator at new location away from the window. Refer to M&E spec.

Ground Floor - Survey of building carried out on 27 February 2009. To be read in conjunction with WMP 4921- L (01) 03

### Room G1 - Images




Room	Walls	Floor	Ceiling	Door/Ironmongery	Window	Fixtures/Fittings	Notes
G2 Exist.	Masonry / Lath & plaster. White emulsion paint on Walls paper.	Timber floor Carpet finish	Lath & plaster. White emulsion.	Glazed flush fire door Georgian wire. Gloss paint finishes several coats. Ironmongery- old satin SS door handle of no historic importance.	Casement window secondary glazing on <b>W3</b> . Crittall window	W1- IT cupboard, Air con Pipe works at low level. Skirting – 100mm High painted pencil round skirting in white gloss. W4- Air vent at high level.	Plastic trunking on top of skirting. Floor Standing Cast Iron Radiator. Stone Fire place on <b>W4</b> boarded over.
G2 Prop.	Strip walls of wallpaper and M&E services. Repair cracks and stop in holes. Make good walls, Skim walls Decorate as spec <b>M60</b> .	Remove exist. Carpet, Rid the floor of glue, staples etc Prepare floor and install new carpet flooring as spec <b>M50</b> .	Skim finish <b>M20</b> Install new M&E services. Prepare and decorate as spec <b>M60</b> .	Door closer Retain doorframe, lining architrave. Supply and fit new 4-panelled fire doors to spec L20 complete with Ironmongery as spec. P21. Refer to door/Ironmongery schedule	Prepare and redecorate existing cills Decorate existing Crittall windows as spec M60.	Retain A/C and IT cabinet and re-route cabling. New M&E Services (Refer to M&E spec) Strip out existing skirting and install Ogee skirting and decorate as spec <b>M60</b> .	Install new steel radiator. Refer to M&E spec. Allow for dado trunking.

Room G2 - Images




Room	Walls	Floor	Ceiling	Door/Ironmongery	Window	Fixtures/Fittings	Notes
G3 Exist.	Masonry, Lath & plaster. Emulsion	Timber floor Carpet finish	Lath & plaster. White emulsion.	Non- glazed Fire door. Gloss paint finishes	Casement window secondary glazing on	W1- Wall mounted Air con Unit	Plastic trunking on top of skirting.
	paint on Wallpaper.			several coats. Ironmongery- old satin SS door handle of no historic importance. Door closer	<b>W3</b> . Crittall window frames	Skirting – 100mm High painted pencil round in white gloss. <b>W2</b> - Air vent at high level. Shelving for the length of wall.	Floor Standing Cast Iron Radiator. Stone Fire place on <b>W4</b> boarded over.
G3 Prop.	Strip walls of wallpaper and M&E services. Repair cracks and stop in holes. Make good walls, Skim walls Decorate as spec <b>M60</b> .	Remove exist. Carpet, Rid the floor of glue, staples etc Prepare floor and install new carpet flooring as spec <b>M50</b> .	New M&E service installations refer to M&E spec. Skim finish <b>M20</b> Prepare and decorate as spec <b>M60</b> .	Retain doorframe, lining architrave. Supply and fit new 4-pannelled fire doors to spec L20 complete with Ironmongery as spec. P21	Refurbish existing windows as spec. L10. Decorate frame and Architrave.	Strip out shelving noggins. Strip out existing skirting and install Ogee skirting and decorate as spec M60.	Install new steel radiator. Refer to M&E spec. Allow for dado trunking.

Room G3 - Images



Room	Walls	Floor	Ceiling	Door/Ironmongery	Window	Fixtures/Fittings	Notes
G4	Lath & plaster.	Timber floor	Lath & plaster.	Fire door Upper.	Sash window on <b>W3</b> .	W1 - Retain and	Redundant power sockets and
Exist.	White emulsion paint on Walls paper.	Carpet finish	Wall papered and painted in white emulsion. Decorative plaster coving	Single pane Georgian wire. Gloss paint finishes several coats. Ironmongery- old satin SS door handle of no historic significance.	Timber panelled reveal. Cills in poor condition. Timber Panelling on reveals	redecorate service pipes at high-level length of room. Skirting – 230mm High Ogee painted in white gloss. <b>W4</b> - Marble fire surround. Fireplace boarded up and air vent above.	discontinued metal trunking remain on walls. Floor Standing Cast Iron Radiator. Stone Fire place.
G4 Prop.	Strip walls of wallpaper and M&E services. Repair cracks and stop in holes. Make good walls, Skim walls Decorate as spec M60.	Remove exist. Carpet, Rid the floor of glue, staples etc Prepare floor and install new carpet flooring as spec <b>M50</b> .	Strip ceiling of wallpaper. New service installations refer to M&E spec. Skim finish <b>M20</b> Prepare and decorate as spec <b>M60</b> .	Retain doorframe, lining architrave. Provide new 4- panelled door spec L20 complete with Ironmongery P21.	Refurbish windows. Prepare and decorate timber reveal panelling, under window panel and window cills as spec <b>M60</b> .	Supply and fix Ogee skirting to match and decorate as specified. Form opening for lift door on <b>W1</b> at the corner with <b>W4</b> .	Strip out existing radiator and Install new steel radiator. Refer to M&E spec. Allow for dado trunking. Form opening on floor, ceiling and wall <b>W4</b> at door height for disabled lift. Store floor joists and materials for future restoration

#### **ROOM 4 - IMAGES**



Room	Walls	Floor	Ceiling	Door/Ironmongery	Window	Fixtures/Fittings	Notes
G51 Exist.	Masonry wall. Emulsion painted and Tiled finishes.	Timber floor Vinyl finish	Concrete slab. Emulsion paint finish.	Solid core Flush door Gloss paint finishes several coats. Ironmongery- old satin SS door handle of no historic significance.	Single glazed timber framed window on <b>W4</b> . Architrave to all sides of opening.	Wall & Floor mounted Sanitary ware. Wall mounted soap dispenser, paper towel dispenser, Radiator etc.	New layout to form a disabled toilet.
G51 Prop.	Strip out M&E services. Strip out wall tiles. Repair cracks and stop in holes. Make good walls, Skim walls as Spec M20 Decorate as spec M60	Strip out vinyl flooring coving etc. Rid the floor of glue, staples etc prepare floor as specified and install new vinyl flooring.	New false ceiling as spec <b>K40</b> New extract fan on ceiling and duct out thro' void and hole in wall at H/L. Refer to M&E spec.	Retain doorframe, lining architrave. Provide new 4-panelled door complete with Ironmongery as <b>P21</b>	Refurbish existing windows as spec. <b>L10</b> . Decorate frame and Architrave.	New Sanitary appliances as spec. <b>N13</b> .New PTD, SD and hand dryer.	Demolish internal walls. Construct new walls (new layout) to form two WC cubicles. Refer to M&E spec. for new M&E services.

**ROOM 51 IMAGES** 



Room	Walls	Floor	Ceiling	Door/Ironmongery	Window	Fixtures/Fittings	Notes
G52 Exist.	All walls white emulsion paint on Walls paper.	Timber floor Vinyl finish	Lath & plaster. Wall papered and painted in white emulsion. Decorative plaster coving	Timber framed glazed Entrance door with side panel. Gloss finish. Internal Flush doors to basement and WC. Ironmongery- old satin SS door handle of no significant historic value.	None	Skirting – 230mm Ogee in green gloss finish.	Plastic trunking on top of skirting. Floor Standing Cast Iron Radiator supported on <b>W2</b> .
G52 Prop.	Strip out services. Strip wallpaper. Repair cracks and stop in holes. Make good walls, Skim walls as Spec M20 Decorate as spec M60	Remove exist. Vinyl, did the floor of glue, adhesive etc prepare floor and install new entrance matting Carpeting as spec. <b>M50</b>	In hall way and landing, Strip ceiling of wallpaper. New service installations refer to M&E spec. Skim finish <b>M20</b> Prepare and decorate as spec <b>M60</b> .	Retain doorframe, lining architrave. Supply and fix new entrance door and side panel as Spec L20. New 4-panelled Internal door to WC & basement. Ironmongery as spec P21.		Decorate existing skirting as spec <b>M60</b> . New service cupboard to house services and panels	Strip out M&E services and trunking. New M&E services. Refer to M&E spec for new services. <u>In corridor area-</u> New false ceiling with plasterboard margin and coving on all sides and lay-in metal planks in the middle of corridor as spec K10 & K40 (Typical details)

### **ROOM 52 IMAGES**



Room	Walls	Floor	Ceiling	Door/Ironmongery	Window	Fixtures/Fittings	Notes
G53 Exist.	Masonry/ lath & plaster. Emulsion painted and Tiled finishes.	Timber floor Vinyl finish	Concrete slab. Emulsion paint finish.	Solid core Flush door Gloss paint finishes several coats. Ironmongery- old satin SS door handle of no historic significance.	Single glazed timber framed window with air vent on <b>W4</b> . Architrave to all sides of opening.	Wall & Floor mounted Sanitary ware. Wall mounted soap dispenser, paper towel dispenser, Radiator etc.	Wall mounted cast iron radiator. Supply and waste pipes.
G53 Prop.	Strip out M&E services. Strip out wall tiles. Repair cracks and stop in holes. Make good walls, Skim walls as Spec M20 Decorate as spec M60	Strip out vinyl flooring coving etc. Rid the floor of glue, staples etc prepare floor and install new vinyl flooring as spec. <b>M50</b>	Repair cracks and stop in holes. Make good walls, Skim Skim finish Prepare and decorate as Spec M20	Retain doorframe, lining architrave. Provide new 4-panelled door complete with Ironmongery as <b>P21</b>	Refurbish existing windows and redecorate as spec L10.	Supply and fix coved skirting as spec <b>M50</b> . New Sanitary appliances as spec. <b>N13</b> .New PTD, SD and hand dryer.	Refer to M&E spec. For new M&E services.

**ROOM 53 IMAGES** 



Room	Walls	Floor	Ceiling	Door/Ironmongery	Window	Fixtures/Fittings	Notes
G54 Exist.	Masonry, white emulsion paint finish. Wall papers	Timber floor Vinyl finish.	Lath & plaster. White emulsion.	Timber framed glazed Entrance door with side panel. Green colour gloss paint finishes Several coats. Ironmongery- old satin SS door handle of no significant historic value.	High-level glazing.	Skirting – 230mm Ogee in green gloss finish. Staircase	Plastic trunking on top of skirting. Floor Standing Cast Iron Radiator supported on <b>W2</b> .
G54 Prop.	Strip out services repair cracks and stop in holes. Make good walls, Skim walls <b>M20</b> Decorate as spec <b>M60</b>	Remove exist. Vinyl, did the floor of glue, adhesive etc prepare floor and install new carpet flooring as spec. <b>M50</b>	In hall way and landing, Strip ceiling of wallpaper. New service installations refer to M&E spec. Skim finish <b>M20</b> Prepare and decorate as spec <b>M60</b> .	Retain existing door, frame, lining & architrave. Decorate as <b>M60</b> . Retain existing Ironmongery. New 4- panel internal doors ( <b>L20</b> )	Prepare and redecorate High-level Glazing as spec <b>M60</b> .	Supply and fix Ogee skirting to match existing and decorate as spec <b>M60</b> . Refurbish and redecorate staircase.	Strip out existing radiator and Install new steel radiator. Refer to M&E spec. Allow for dado trunking. Redecorate

### ROOM 54 - IMAGES



Room	Walls	Floor	Ceiling	Door/Ironmongery	Window	Fixtures/Fittings	Notes
G55 Exist.	Lath & Plaster with emulsion paint finish. Service trunking at high level.	Timber floor Vinyl finish	Lath & plaster. White emulsion.	Timber flush fire door with Georgian wired glass pane and 4-panel fire door with Georgian wired glazing on top. Ironmongery- old satin SS door handle of no significant historic value.	None	Skirting – 100mm pencil round in white gloss finish. Wall mounted fire extinguishers, file trays notice board.	New false ceiling incorporated to hide the M&E services
G55 Prop.	Strip out all M&E services repair cracks and stop in holes. Make good walls, Skim walls <b>M20</b> Decorate as spec <b>M60</b> Service penetration thro' corridor wall at H/L above false ceiling level.	Remove exist. Vinyl, rid the floor of glue, adhesive etc prepare floor and install new Carpet flooring as spec. <b>M50</b>	In hall way and landing, Strip ceiling of wallpaper. New service installations refer to M&E spec. Skim finish <b>M20</b> Prepare and decorate as spec <b>M60</b> .	Supply and fix new 4 panel internal doors, doorframe, lining architrave. Provide new Front door and side panel spec. (L20) complete with Ironmongery (P21).	End of corridor on all floor:- Form opening in floor and ceiling at and construct new full height service encasement. Decorate to match adjacent wall.Allow access to services.	Strip out fixtures and fittings. Hand Fire extinguishers to CA to be reused on completion of project. Supply and fix 230mm high Ogee skirting to match and decorate as specified (M60).	Strip out M&E services and trunking. New M&E services. Refer to M&E spec for new services. <u>In corridor area</u> , New false ceiling with plasterboard margin and coving on all sides and lay-in metal planks in the middle of corridor as spec K10 & K40 (Typical details)

### **ROOM 55 - IMAGES**



First Floor - Survey of building carried o	ut on 27 February 2009. To be read in	conjunction with WMP 4921- L (01) 05
	····	

Room	Walls	Floor	Ceiling	Door/Ironmongery	Window	Fixtures/Fittings	Notes
1.1	Lath & Plaster	Timber floor	Lath & plaster.	Old 4 panelled fire door	Sash window on <b>W4</b> .	Skirting – 230mm High	Redundant power
Exist.	emulsion paint on Wallpaper. Heating pipes at low level.	Carpet finish	Poor finish. Appear crumbling. Wall papered and painted in white emulsion. Decorative plaster coving	Upper Georgian wire - glazed panes (longer). Several coats Gloss paint finishes. Ironmongery- old satin SS door handle of no historic importance.	Georgian glazing bars. Timber window cills in poor condition. Timber Panelling on reveals	Ogee painted in white gloss. 100mm pencil round on <b>W4</b> white. Stone Fireplace boarded up and air vent above. Wall shelving.	sockets and discontinued metal trunking remain on walls. Floor Standing Cast Iron Radiator. Stone Fire place.
1.1 Prop	Strip out M&E services. Strip walls of wallpaper. Repair cracks and Make good walls, Skim <b>M20</b> Decorate as spec <b>M60</b> .	Remove exist. Carpet, Rid the floor of glue, staples etc Prepare floor and install new carpet flooring as spec <b>M50</b> .	Strip ceiling of wallpaper. Allow for the installation of new services. Skim finish <b>M20</b> Prepare and decorate as spec <b>M60</b> .	Retain doorframe, lining architrave. Provide new matching 4-panelled fire door spec L20 complete with Ironmongery P21.	Refurbish Sash window. Restore timber frame and surround. Prepare and redecorate existing window and secondary glazing and cills as spec <b>M60</b> .	Remove shelving and noggin. Repair cracks and Make good walls. Retain Ogee skirting on W1, W2 & W3.Replace skirting on W4 with matching Ogee skirting. Decorate fireplace and walls as spec. M60	Allow for dado trunking. Provide new steel radiator at new location away from the window. Refer to M&E spec. Radiator.

### Room 1.1 - Images

