



RECEIVED 24 APR 2009

Photograph No. 10 – Junction of Ceiling, “boxing” around pipes and south & east walls
Living Room - 29 Buckridge Building



**Photograph No – 11 Junction of ceiling and south & west walls
Living Room - 29 Buckridge Building**



**Photograph No. 12 – Junction of ceiling and north wall
Living Room - 29 Buckridge Building**



**Photograph No. 13 – Skirting board to west wall
Living Room - 29 Buckridge Building**



**Photograph No. 14 – Skirting board to south wall and chimney breast
Living Room - 29 Buckridge Building**



**Photograph No. 15 – Junction of ceiling and west wall
Bedroom - 29 Buckridge Building**



**Photograph No. 16 – Junction of Ceiling, “boxing” around pipes and north & east walls
Bedroom - 29 Buckridge Building**



**Photograph No. 17 – Skirting board to north wall
Bedroom - 29 Buckridge Building**