

Photograph 1: Front Door. Replacement door to be replaced with a new hardwood door.



RECEIVED
18 DEC 2007


Photograph 2: Internal hall door and cupboard door. Panelled internal door to remain, cupboard door to be replaced with new door to match hallway door.




Photograph 3: Ground floor toilet door. To be replaced with new door to match other panelled doors within property.



Photograph 4: Ground floor utility room and cupboard doors. Both doors to be replaced to match other panelled doors on site.




Photograph 5: Ground floor living room door to be retained.



Photograph 6: Replacement kitchen door to be removed and replaced with new door to match other panelled doors on site.



Photograph 7: Replacement kitchen door to be removed and replaced with new door to match other panelled doors on site.



Photograph 8: First floor bedroom door to be retained.



Photograph 9: First Floor bathroom door to be retained



Photograph 10: Replacement first floor bedroom door to be replaced with a panelled door to match others within property.

