

Photographs
marked with
my comments.
Respect
Simon Freeman
27 Blade Walk

on roof of No 27 -
looking towards 29


Front of
house



1.

Open roof hatch is 27 Blade Walk
Picture shows high retaining wall of
#29

Increased wall height
of No 29 →
original height of →
side wall of #27



2.

Photographs
marked with
my comments.
Regards
Simon Freeman
27 Park W.

Roof of No. 25




3.



Show 25 + 23 and highlights
the bulk of the roof at #23

4.

Roof of 23 - looking to rear




5.

No 23 rear of roof



6.

Roof of 23 looking forward to
Plastic Walk.



This shows that
The roof of 23
is built right up
to the top of
the front
parapet wall

7.