



Photo 1: Rear boundary wall between No. 27 Church Row and 27 Perrins Walk to be demolished.




Photo 2: Rear boundary wall showing poor structural condition.

PROJECT	27 Church Row, Hampstead, London NW3
TITLE	Photographs of Walls
CLIENT	Mrs Deborah Davis
SCALE	NTS
DATE	November 2007
DRG NO.	862
jb planning associates Chells Manor, Chells Lane, Stevenage, SG2 7AA e-mail info@jbplanning.com url www.jbplanning.com tel 01438 312130 fax 01438 312131	
© Crown copyright All rights reserved Licence No. 100039935	

RECEIVED
12 NOV 2007



Photo 3: Rear boundary wall showing single skin construction.



Photo 4: Rear boundary wall – detail of structural failure.

PROJECT	27 Church Row, Hampstead, London NW3
TITLE	Photographs of Walls
CLIENT	Mrs Deborah Davis
SCALE	NTS
DATE	November 2007
DWG NO.	862
jb planning associates Chells Manor, Chells Lane, Stevenage, SG2 7AA e-mail info@jbplanning.com url www.jbplanning.com tel 01438 312130 fax 01438 312131 © Crown copyright All rights reserved Licence No. 100039035	

RECEIVED
12 NOV 2007



Photo 5: Intermediate garden wall (1990's) to be demolished.




Photo 6: Intermediate garden wall (1990's) to be demolished.

PROJECT	27 Church Row, Hampstead, London NW3
TITLE	Photographs of Walls
CLIENT	Mrs Deborah Davis
SCALE	NTS
DATE	November 2007
DRG NO.	862
jb planning associates Chells Manor, Chells Lane, Stevenage, SG2 7AA e-mail info@jbplanning.com url www.jbplanning.com tel 01438 312130 fax 01438 312131	
© Crown copyright All rights reserved Licence No. 100039635	

RECEIVED
12 NOV 2007