Hockley & Dawson Consulting Engineers Limited

The British Museum Conservation Report Fire Door Photographs

R I V

8

e la

9 NOV 200

0



Style of existing fire door and framing used on third floor to be used in new second floor opening.




Style of existing fire door and framing used on third floor to be used in new second floor opening.



14725 Fire Door Photos/HD

Page 1 of 1



DO NOT SCALE THIS DRAWING





admin@hockleyanddawson.co.uk

www.hockleyanddawson.co.uk

Consulting Engineers Hockley & Dawson Consulting Engineers Limited The Great Barn Smithbrook Barns Cranleigh Surrey GU6 8LH