

SHEET 1: 16 DENNINGTON PARK ROAD – FRONT



16 Dennington Park Road - Front



Front Windows - Upper Ground Floor



Front Windows – Upper Ground Floor

SHEET 2: 16 DENNINGTON PARK ROAD – BACK



BACK OF FLAT
(window on left of door partially obscured by tree)



BACK WINDOW



BACK – SLIDING DOOR

SHEET 3: 16 DENNINGTON PARK ROAD – DAMAGE TO WINDOWS



FRONT WINDOW - INSIDE



BACK DOOR - OUTSIDE

SHEET 4: 14 & 16 DENNINGTON PARK ROAD COMPARED



FRONT OF NUMBER 14 (situated on the right hand side of 16 Dennington Park Road)



FRONT OF NUMBER 16 in comparison