




Photo 3: Concrete base beneath tank 2.



Photo 4: Removal of tank 3.



Photo 5: Ground beneath the base of tanks 3 and 4.



Photo 6: Removal of tank 8.



IAN FARMER
ASSOCIATES

SITE

Job no.

50



Photo 7: Staining on concrete base beneath tanks 7 and 8.




Photo 8: Contaminated water in trial pit to the east of interceptor.



Photo 1: Exposed ground around tanks 1 and 2 (20/06/07).



Photo 2: Tank 2 following removal of tank 1 and solid contents (31/07/07).




Photo 3: Concrete base beneath tank 2.



Photo 4: Removal of tank 3.




Photo 5: Ground beneath the base of tanks 3 and 4.



Photo 6: Removal of tank 8.




Photo 7: Staining on concrete base beneath tanks 7 and 8.




Photo 8: Contaminated water in trial pit to the east of interceptor.