

APPENDIX C

PHOTOGRAPHS 23RD MARCH, 2006

6323/JSJ/VME
27 March 2006

HAMPSTEAD SYNAGOGUE

SCHEDULE OF PHOTOGRAPHS
JSJ INSPECTION ON THURSDAY 23RD MARCH, 2006


P301	Decorative plasterwork at west end of dome.
P302	North west rib of dome.
P303	North west rib of dome.
P304	North west rib of dome.
P305	Top of dome.
P306	Top of dome.
P307	Top of dome.
P308	Top of dome.
P309	Underfloor void at west end. TP7.
P310	Underfloor void at west end. TP7.
P311	Underfloor void at west end. TP7.
P312	View of TP7.
P313	View into PT8 – north wall – new escape door TP8.
P314	View into PT8 – north wall – new escape door TP8.
P315	Severely decayed bearer timber TP8.
P316	View looking south under floor from TP8.
P317	North wall – water overflow – Near G6.
P318	North wall outside TP8.
P319	From TP10 looking under floor from Room B3.
P321	From TP10 looking under floor from Room B3.
P322	From TP11 into rubble fill – from room B3.
P323	Duct from B3 under floor of G9.
P324	Duct from B3 under floor of G9.
P325	Shrub in east parapet of tower.
P326	North face of tower.
P327	West face of tower.
P328	West face of tower.
P329	West face of tower.
P330	West window.
P331	West window.
P332	Looking from TP7 into rubble fill under G2.
P333	Looking from TP7 into rubble fill under G2.
P334	Looking from TP9 into soil fill under G4.
P335	Looking from TP9 into soil fill under G4.
P336	Crack in wall of G4, above false ceiling.
P337	Roofs – looking south east.
P338	North parapet.
P339	North parapet daylight through bricks.
P340	Inside top of dome.
P341	Inside top of dome – steel framing.
P342	South east turret.
P343	South west turret.
P344	North window in east face of tower.
P345	North window in east face of tower.
P346	North parapet.
P347	Motorcycle blocking fire escape on West End Lane.



P301




P302




P303




P304




P305




P306




P307




P308




P309




P310




P311




P312




P313



P314



P315



P316




P317




P318



P319




P320




P321




P322



P323



P324



P325



P326




P327




P328



P329



P330




P331




P332




P333




P334




P335




P336




P337




P338




P339



P340




P341




P342




P343




P344



P345



P346



P347