

Existing Windows No.13 Langleid Gardens

No. 15

No. 13



Side dormer window
Obscured Glass.
Communal staircase
behind

Fixed rooflight with
obscured glass.
Bedroom behind

Image 1: Relationship between existing side dormer windows at No.15 & No.13
NOTE: This is not a visible view. Photograph taken by extending camera over balcony at No. 15 to demonstrate level difference between dormers.



Side dormer window
Obscured Glass.
Communal staircase
behind.

Image 2: From side bedroom window @ No.15 towards side dormer window @ No.13



Image 3: View from side bedroom window @ No.15 towards No.13



Image 4: View towards side of No.13 from garden side

Schott ETC 16 Solar Collector`



Image 5: Example of Schott Solar Thermal panels installed.