



EXTERNAL ENTRANCE



GROUND FLOOR LOBBY



1ST FLOOR ENTRANCE FROM  
BELOW



1ST FLOOR ENTRANCE FROM  
ABOVE



2ND FLOOR ENTRANCE  
SHOWING EXISTING WALL  
INFILL ON STAIRWELL

SURVEY PHOTOS

work stage :	SURVEY	job :	64 BELSIZE PARK GARDENS LONDON NW3 4NE	JAS ARCHITECTS	23-28 PENN STREET LONDON N1 5DL UK	<b>NB</b> ALL MATERIALS AND WORKMANSHIP TO BE IN ACCORDANCE WITH BRITISH STANDARDS. MANUFACTURERS RECOMMENDATIONS AND GENERAL GOOD PRACTICE <b>1</b> ALL DIMENSIONS TO BE VERIFIED BY THE CONTRACTOR AND DISCREPANCIES OR OMISSIONS REPORTED TO THE ARCHITECT IMMEDIATELY <b>2</b> THIS DRAWING IS TO BE READ IN CONJUNCTION WITH RELEVANT ENGINEERS DRAWINGS AND IS SUBJECT TO APPROVAL FROM THE STATUTORY AUTHORITIES <b>3</b> COPYRIGHT RESERVED <b>4</b> DO NOT SCALE	Revision :	Revision Date:	Change :
scale :	N/A	title :	SURVEY PHOTOS		T/F 44 (0) 20 7739 8361 E jasarchitects@aol.com				
drawn by :	ji								
date :	09.10.2006								
original sheet size :	A3	dwg no:	140/001pht						