




Picture of wardrobe to be replaced with hot water tank cupboard of similar construction



Typical skirting board in bedroom 3.




View of wall to be removed – from bedroom 3



View of wall to be removed – from bedroom 2





View of loft hatch that needs to be moved from bedroom 3 to bedroom 2



Typical view of listed terrace (131-149 Prince of Wales Road – odd numbers)