

PHOTO REFERENCE PS/2005/037DB/1000		
PHOTO REF	ROOM No.	VIEW / DESCRIPTION
PHOTO 8230016	304	Photo showing cornice detail. Air con unit and trunking to be fixed to wall.
PHOTO 8230017	304	Photo showing cornice detail. Air con unit and trunking to be fixed to wall.
PHOTO 8230019	303	Photo showing cornice detail. Air con unit and trunking to be fixed to wall.
PHOTO 8230020	303	Photo showing cornice detail. Air con unit and trunking to be fixed to wall.
PHOTO 8230021	303	Photo showing cornice detail. Trunking to be fixed to wall.
PHOTO 8230022	302	Photo showing cornice detail. Trunking to be fixed to wall.
PHOTO 8230023	302	Photo showing cornice detail. Air con unit and trunking to be fixed to wall.
PHOTO 8230024	302	Photo showing cornice detail. Air con unit and trunking to be fixed to wall.
PHOTO 8230025	WC	Typical photo of wall used throughout
PHOTO 8230026	WC	Typical photo of wall showing riser access panel used throughout
PHOTO 8230027	301	Photo showing cornice detail. Air con unit and trunking to be fixed to wall. Vertical condensate discharge pipe.
PHOTO 8230028	204	Photo showing cornice detail. Air con unit and trunking to be fixed to wall.
PHOTO 8230029	203	Photo showing cornice detail. Air con unit and trunking to be fixed to wall.
PHOTO 8230030	203	Trunking to be fixed to wall.
PHOTO 8230031	203	Trunking to be fixed to wall.
PHOTO 8230032	202	Trunking to be fixed to wall.
PHOTO 8230033	202	Trunking to be fixed to wall.
PHOTO 8230034	202	Photo showing cornice detail. Air con unit and trunking to be fixed to wall.
PHOTO 8230035	201	Photo showing cornice detail. Air con unit and trunking to be fixed to wall.
PHOTO 8230036	103	Photo showing cornice detail. Air con unit and trunking to be fixed to wall.
PHOTO 8230037	103	Trunking to be fixed to wall.
PHOTO 8230038	103	Trunking to be fixed to wall.
PHOTO 8230039	104	Photo showing cornice detail. Air con unit and trunking to be fixed to wall.
PHOTO 8230042	102	Trunking to be fixed to wall.
PHOTO 8230043	102	Photo showing cornice detail. Air con unit and trunking to be fixed to wall.
PHOTO 8230044	102	Photo showing cornice detail. Air con unit and trunking to be fixed to wall.
PHOTO 8230045	101	Photo showing cornice detail. Air con unit and trunking to be fixed to wall.
PHOTO 8230046	G01	Photo showing cornice detail. Air con unit and trunking to be fixed to wall.
PHOTO 8230047	G02	Photo showing cornice detail. Air con unit and trunking to be fixed to wall.
PHOTO 8230048	WC	Photo showing wall and access panel to riser
PHOTO 8230049	WC	Photo showing basin for condensate drain to discharge into basin via tundish
PHOTO 8230050	TEAPOINT	Photo showing sink for condensate drain to discharge into basin via tundish

London Borough of Camden
ENVIRONMENT DEPT.

03 AUG 2006

PLEASE RETURN

PHOTO REFERENCE PS/2005/037DB/1000

PHOTO REF	ROOM No.	VIEW / DESCRIPTION
PHOTO 8230051	GO4	Photo showing cornice detail. Vertical condensate discharge pipe.
PHOTO 8230052	GO3	Photo showing cornice detail. Vertical condensate discharge pipe.
PHOTO 8230053	B01	Photo showing cornice detail. Vertical condensate discharge pipe.
PHOTO 8230057	B02	Trunking to be fixed to wall.
PHOTO 8230058	B02	Trunking to be fixed to wall.
PHOTO 8230062	B04	Photo showing cornice detail. Vertical condensate discharge pipe.
PHOTO 8230064	CORRIDOR	Photo of corridor. Trunking to be fixed to ceiling
PHOTO 8230065	CORRIDOR	Photo of corridor. Trunking to be fixed to ceiling
PHOTO 8230068	CORRIDOR	Photo of corridor. Trunking to be fixed to ceiling
PHOTO imag0004	VAULT	Photo of vault door
PHOTO imag0006	VAULT	Photo of lightwell area