

PAR4/PHO/01 8th October 2004

4 Prince Albert Road, Lordon. NW1 7SN

Existing photographic audit of areas affected by the Application proposals




Photo 1
Infilled connecting doorway as viewed from No. 3




Photo 2
Sealed off connecting door viewed from No. 4




Photo 3
Panelled ceiling already divided by existing partitions



St Elmo West Street West Malling Kent. ME19 6QX

Tel: +44 (0)1732 845525 Fax: +44 (0)1732 870964



Gerry Rogerson BA Dip (Hons) Arch RIBA gerry@rogersonlimited.com



Ali Rogerson BSc MRICS ali@rogersonlimited.com

Company No. 4418314 VAT No. 781 2961 10




Photo 4
Over panelled wall in office to accommodate partition




Photo 5
Area of wall in corridor to be over panelled as detail in Photo 4 above



Photo 6
Stairway from ground floor Reception and leading to lower ground floor




Photo 7
Bulkhead and cornice detail over stairway / proposed kitchen door location



Photo 8
Balustrade base plate and string detail




Photo 9
Half landing at floor of main s air flight from Reception




Photo 10
Low level casings in Female V/C, containing stub stack on soil waste pipe;
Cold water supply visible between this casing and service riser to left