






102 CAMLEY STREET

PHOTOGRAPH OF THE OBLIQUE BRIDGE

234937-00 FIGURE 18







102 CAMLEY STREET

DRAWING OF THE DETAILS OF THE OBLIQUE BRIDGE

234937-00 FIGURE 19






ARUP

102 CAMLEY STREET


PHOTOGRAPHS OF THE RAILWAY BRIDGE

234937-00 FIGURE **20**



Source: CTRL Drawing Number 103-DTB-06850-95510-Z0






102 CAMLEY STREET

TUNNEL ADJACENT TO 102 CAMLEY STREET

234937-00

FIGURE 21




Source: CTRL Drawing Number 103-DTB-06850-95511-Z0



102 CAMLEY STREET

CROSS SECION THROUGH THAMESLINK SOUTH OF SITE

234937-00 FIGURE 22




1994 British Geological Survey © NERC. All rights reserved

102 CAMLEY STREET
GEOLOGICAL MAP

ARUP

234937-00 FIGURE **23**



ARUP

102 CAMLEY STREET

EXCERPT FROM THE LOST RIVERS OF

LONDON

234937-00 FIGURE **24**






ARUP

102 CAMLEY STREET

PHOTOGRAPHS OF FOOTINGS OUTSIDE WAREHOUSE ON 102 CAMLEY STREET


234937-00

FIGURE 25





102 CAMLEY STREET BOMB RISK MAP



Colour Key References (for guidance only)

Black Total destruction

Purple Damaged beyond repair

Dark Red Seriously damaged; doubtful if repairable

Light Red Seriously damaged, but repairable at cost Orange General blast damage – not structural

Yellow Blast damage, minor in nature

Light Blue Clearance areas

Light Green Clearance areas



V1 flying bomb



ARUP

102 CAMLEY STREET

EXCERPT FROM BOMB DAMAGE MAPS FOR LONDON

234937-00

FIGURE 27