



This window was for many years covered on the inside and still retains it's brown graining layer on that face. The woodwork of the frame is largely complete but in need of refurbishment.



Luard Conservation Limited 67 Selkirk Avenue London NW10 4HJ  +44 (0)20 8961 7544 +44 (0)7963 741 117 info@luardconservation.com	The Elms, Fitzroy Park		
	EW/G.26		
	NOT TO SCALE		