No.3 Certificate of Survey of Structure Reference: D.S. ....

## To the CAMDEN BOROUGH COUNCIL

London Building Acts (Amendment) Act, 1939: Part VII London County Council (General Powers) Act, 1955: Part II and 1958: Part III

## **DANGEROUS STRUCTURES**

Having made a Survey of the Structure known as

52 St Giles High Street, WC2.

in the London Borough of Camden as required by the Camden Borough Council, I hereby certify my opinion that the said Structure is in a dangerous state: and that the Owner should be required forthwith to take down repair or otherwise secure such parts of the back addition roof construction also the floor constructions to the rear rooms at ground and first floor levels also the enclosing rear valls of the back addition where loose sagged partly collapsed materially damaged by fire insecure inadequately supported or otherwise dangerous and to all other work found necessary in consequence of the foregoing.

## Owner's Name and Address

Mark BULLUS 57 Oval Mansions Vauxhall Street, London, SE11

Area of Structure: greater/less, than 4 squares.

Number of Storeys STX

\* Length of time which may be reasonably allowed for the execution of Works .....adays.

The premises are occupied not occupied

Dated this 24th day of February **19**87

District Surveyor

NOTES-Please state whether the Council's contractors have been instructed

(i) under Section 61(4) of the 1939 Act, to remove immediate danger

(ii) under Section 62(2) of the 1939 Act, to erect shoring

(iii) under Section 62(2) of the 1939 Act, to hoard in the structure.

Yes/Nox† Yes/100 †

Xes/No †