



Photo Package

33 CHESTER TERRACE, REGENTS PARK



EXTERNALS



1 Front elevation of number 33 Chester Terrace.



2 Looking at one of the 2 Corinthian arched entrances to Chester Terrace.



3 Taken from outside number 33 looking towards the north entrance archway



4 Lower Level Courtyard, Giving access to underground vaults.



EXISTING LOWER GROUND FLOOR



1 Front room, former staff bedroom, lower ground floor




2 Staff kitchen, looking towards the external access to the lower courtyard and vaults



3 Staff kitchen, looking through into the hallway.



4 Hallway, looking towards the staff kitchen with the lift located to the right.



5 View from the hallway looking towards the access staircase.




EXISTING GROUND FLOOR




1 View from the ground floor entrance lobby towards the lift and main staircase.




2 Main ground floor kitchen,



3 View from the main entrance door, looking through the main lobby and up the main staircase.



4 Looking from the doorway of the kitchen towards the main entrance door.



5 View of the large windows in the dining room.



EXISTING FIRST FLOOR



1 View of the main living room with floor to ceiling windows.




2 View of the main living room, looking from the windows through to the stairs and tv room.



3 View from the main staircase, looking through into the main living room



4 View from the TV room, looking towards the dividing wall and doorway leading into the main living space.



5 View from the entrance to the living space up the main staircase.



EXISTING SECOND FLOOR



1 View of the main master bedroom, looking towards the entrance to the dressing room.




2 View of the main master bedroom showing the existing steps and windows.



3 View looking at the entrance door leading to the dressing room and master bathroom



4 View in the main master bathroom,



5 View from the main staircase looking towards the staircase that provides access to the third floor




EXISTING THIRD FLOOR




1 View in the largest bedroom, towards the doorway, and attached ensuite.




2 View from the front bedroom looking through the doorway towards the lift and staircase.



3 View from the third floor hallway looking towards the front window of the bedroom.



4 View from bathroom through the corridor.



5 View of the larger bedroom at the rear of the house.



UNAUTHORIESED STAIRCASE AND ROOFLIGHTS



1 View from the top of the wooden roof access stair, showing treads



2 View from the top of the wooden roof access stair, showing treads



3 View looking up towards the roof access hatch



4 View from the third floor looking up the roof access stair.



5 View from the bathroom looking at the roof light.

