

Dimensions to be verified on site.
Figured dimensions to take preference to those scaled.

This Drawing is the property of CHARLES FUNKE ASSOCIATES.
Copyright is reserved by them and the drawing is issued on the condition that it is not copied, reproduced, retained or disclosed to any unauthorised person, either wholly or in part without the consent in writing of Charles Funke Associates.

1st Floor 75-81 High Street Godalming Surrey GU7 1AW
Telephone: (01483) 608 890. Fax: (01483) 608 920.
e-mail: mail@charlesfunke.com web: www.charlesfunke.com


Key:

- Tree Canopy
- Tree RPA
- Site Boundary

NOTE:

There are no trees within the site boundary. Those trees surveyed are in proximity to the site and are established street trees.

Refer to Charles Funke Associates documents;
770-0013 Tree Survey Document
770-0014 Tree Protection Document
770_PH4_LAN_PLN_003 Tree Protection Plan



Tree No.	Species	Height (m)	DBH (cm)	Form	Health	Location	Notes
1	Platanus hispanica	10.0	15.0	Good	Good	University Street	...
2	Platanus hispanica	10.0	15.0	Good	Good	University Street	...
3	Platanus hispanica	10.0	15.0	Good	Good	University Street	...
4	Platanus hispanica	10.0	15.0	Good	Good	University Street	...
5	Platanus hispanica	10.0	15.0	Good	Good	University Street	...
6	Platanus hispanica	10.0	15.0	Good	Good	University Street	...
7	Platanus hispanica	10.0	15.0	Good	Good	University Street	...
8	Platanus hispanica	10.0	15.0	Good	Good	University Street	...
9	Platanus hispanica	10.0	15.0	Good	Good	University Street	...
10	Platanus hispanica	10.0	15.0	Good	Good	University Street	...

BS5837:2012 Cascade chart for tree quality assessment			
Category & Definition	Criteria (including subcategories where appropriate)	Identification on plan	
Trees unsuitable for retention			
Category D	These are such a condition that they cannot be retained. They are considered as dead trees in the context of this survey. They are not to be retained and should be removed as soon as possible.	Red on plan R08 027A-D	
Trees to be considered for retention			
1. Many arboricultural qualities 2. Mainly landscape qualities 3. Mainly cultural values, including conservation			
Category A	These are trees of high quality with an average canopy height of at least 10m.	Light Green R08 027A-C	
Category B	These are trees of moderate quality with an average canopy height of at least 6m.	Blue R08 027A-B	
Category C	These are trees of low quality with an average canopy height of at least 3m.	Dark Green R08 027A-A	

REVISION _____ DATE _____

CHARLES FUNKE ASSOCIATES
CHARTERED LANDSCAPE ARCHITECTS

Telephone: (01483) 429890 Fax: (01483) 609920 e-mail: mail@charlesfunke.com
1st Floor 75-81 High Street Godalming Surrey GU7 1AW

CLIENT	UCLH		
PROJECT	Proton Beam Therapy (The Rosenheim Building)		
DRAWING TITLE	Existing Tree Survey		
DRAWING STATUS	FOR PLANNING		
COMP. FILE NAME	770_PH4_LAN_PLN_002		
DRAWN BY	BS/MY	CHECKED BY	DR
SCALE	1:250 @ A1	DATE	JULY 2014
DRAWING NO.	770_PH4_LAN_PLN_002	REVISION	0