APPENDIX

Borehole Records

Trial Pit Records

Historical Maps

Site Plan



GE	Geotechnical & Environmental Associates	:		Tytten C	hanger House Coursers Road St Albans AL4 0PG	Site 122 Drummond Street, London, NW1 2HN		Number BH1
Excavation Drive-in Wind	Method dow Sampler	Dimens	ions	Ground	Level (mOD)	Client Julia Pyper		Job Number J14127
		Locatio	n	Dates 09	9/05/2014	Engineer Michael Alexander		Sheet 1/1
Depth (m)	Sample / Tests	Water Depth (m)	Field Records	Level (mOD)	Depth (m) (Thickness)	Description		Kater Sater
0.50 2.00 3.50	D		Water strike(1) at 2.50m.		(0.01) 0.01 (0.30) 0.40 (0.30) 0.70 (0.30) 0.70 (0.30) 0.70 (0.30) 0.70 0.70 0.70 0.70 0.70 0.40 0.40 0.70 0.40 0.70 0.40 0.70 0.40 0.70 0.40 0.70 0.40 0.70 0.40 0.70 0.40 0.40 0.70 0.40 0.40 0.70 0.40 0.40 0.70 0.40 0.40 0.70 0.40 0.70 0.40 0.40 0.40 0.70 0.40	Tile Concrete MADE GROUND (greyish light brown gravelly sand fragments of brick) MADE GROUND (greyish very dark brown sandy (clay with fragments of ash, brick and occasional clo) Orange-brown fine to coarse SAND and fine to coar GRAVEL Soft becoming firm brown silty sandy gravelly CLA Firm grey silty fissured CLAY with selenite crystals Complete at 4.00m	d with gravelly linker) arse	
Remarks Borehole col	lapsed to a depth of	3.6 m upc	n completion and water meas	ured at a d	depth of 3.48 m	n	Scale (approx) 1:50	Logged By ME
							J1412	o. 27.BH1



GEN Geotech	nical & mental	Coursers Road	Site	Number
Associat	es	Herts AL4 0PG	122 Drummond Street, London, NW1 2HN	2
xcavation Method Ianual	Dimensions (mm)	Ground Level (mOD)	Client Julia Pyper	Job Number
	Location	Dates	Engineer	Sheet
		00/05/2014	Niekaal Alexander	1/1
<u>PC</u>	<u>an</u>			
<u>Sस्टताः</u>	ر ار	300 A'		
	4	4	A'	
	BRICK WALL		5	Thuck
ß	eicks Notes	1.0.0.D.	TILC OVER CONCRETC, TOP	W INIC C
T	BE CRUMBLY		MADE GROUND 1	
A	NO SOFT BELOW	1600 AAA	PANING SCARS OVER CONCRE	RE .
G	earns rever	1 XX	70 MM THICK	
	T.		MADE GROUND 2	
	1 - ₁₀ 2 - 2 - 2			
				3
MADE	GROUND 1 -	WART BROWN SU	BRICK FRAGMENTS	th0
MADE	Grains 2 -	BLACKISH DARK B FRAGMENTS OF CO	AL, ASH AND BRICKS	มสษ
		n E e spiken E e e		

All dimensions in millimetres					1:20
Sides of trial pit remained stab	le during excavation		14 M.		Logged by
Groundwater not encountered					ME
Groundwater not encountered		 	 		

÷	Historical Mapping Legends		Geotechnical &
Ordnance Survey County Series and Ordnance Survey Plan 1:2,500	Ordnance Survey Plan, Additional SIMs and Supply of Unpublished Survey Information 1:2,500 and 1:1,250	Large-Scale National Grid Data 1:2,500 and 1:1,250	Environmental Associates Historical Mapping & Photography included:
Cuarry Cravel Sand Pit	Clay Pit Clay Pit	Citre Top Sopes Top	Mapping Type Scale Date Pg London 1:2,500 1876 2 London 1:2,500 1896 3 London 1:2,500 1916 4 Historical Aerial Photography 1:1,250 1946 5
Stoping Masonry	ے کی Rock وہ a Boulders کی جب	ියි Rock ය Rock (scattered)	Ordnance Survey Plan 1:1,250 1953 6 Additional SIMs 1:1,250 1955-1990 7 Ordnance Survey Plan 1:2,500 1953-1990 8
الله المعالم ال Marsh Reeds As Osiers	Cliff Top	Desitioned Boulder Scattered)	Ordnance Survey Plan 11:1.20 10:0 10:0 Ordnance Survey Plan 1:1.250 1968 - 1977 10 Ordnance Survey Plan 1:2.500 1970 11 Supply of Upbulished Survey Information 1:2.500 1970 12 Additional SIMs 1:1.250 1970 12
annun 高 電子 名法名 Rough Pasture Furze Wood	Roofed Building Glazed Roof Building	다. Non-Coniferous Tree 속 Coniferous Tree (surveyed) 《surveyed) 《surveyed) 《 (surveyed) 《 《 《 《 《 《 》 》 《 《 》 《 》 《 》 《 》 《 》	Orchance Survey Plan 1:1,250 1986 - 1987 14 Additional SIMs 1:1,250 1986 15 15 Large-Scale National Grid Data 1:1,250 1991 16 Large-Scale National Grid Data 1:1,250 1993 17
້າດີ ຊີ່ຊີສ໌ ແລະ ຈ≎ ຈ Mixed Wood Brustwood Orchard	Top Stoping Archway	္လားေက်း (not surveyed) "ႏိုင္ငံ (not surveyed) သူ Orchard ဖို္္ Scrub ႏြိဳ Bracken	Large-Scale National Grid Data 11:1,250 1993 18 Large-Scale National Grid Data 11:1,250 1996 19
ALA: FIT FOR Stephing	役) Non-Coniferous Tree 条 Coniferous Tree (surveyed) (surveyed)	化 Coppice, w Reeds "她 of t Marsh. Satings	
Ferry A Waterfall Lock	${}_{\rm eff}^{\rm chi}$ Non-Conferous Trees ${}_{\rm eff}$ (not surveyed) (not surveyed)	Grassland with, Heath Culvert	
△ Trig. Station 507 △ Altitude at Trig. Station B.M.3259 ◆ Bench Mark 342 + Surface Level	لي Orchard β Scrub Tree Tree α , Scrub Tree Bracken L. Copplee	۲riangulation مع Antiquity والتعالي Antiquity of water flow ∆ Station مو (site of)	
	Reads Stitute Sattings	— ^E ↑L Electricity Transmission Line ⊠ Electricity Pylon	Historical Map - Segment A13
	Grassland minimum recut. → Direction → B Bench & Antiquity of water flow → B Mark (site of)	A at saten Bench Mark	A21 A22 A23 A24 A25
	Cave A Triangulation B Electricity Entrance Station Pylon	Roofed Building Glazed Roof	
Railway crossing Level Crossing Railway Road Realway	E_1 Electricity Transmission Line County Boundary (Genorablical)	Distriction and and and and and and and and and an	
LIK X	County Scivil Parish Boundary	 Boundary post/stone 	- A6 A7 A8 A10 A10 A10 A10
A Real Provide A Real ProvideA Real ProvideA Real ProvideA Real ProvideA Real Pro	Civil Parish Boundary	Boundary mereing symbol (note: these always appear in opposed pairs or groups of three)	AT A2 A3 A4 A5
raumary crossing road over road over River or Canal single stream River or Canal	Symbol marking point where boundary	Bks Barracks P Pillar, PoleorPost Bty Battery PO Post Office	Order Details
County Boundary (Geographical) County & Civil Parish Boundary	BH BeerHouse P Pillar, Pole or Post BP BS Roundary Poter Strina PC Post Office	Cemy Cemetery PC Public Convenience Chy Chlinney Pp Pump	Urder Number: 55992834_1_1 Customer Ref: J14127 National Grid Reference: 529320, 182550
+ + + + + Administrative County & Civil Parish Boundary	Ch, C Capitan, Crane PC Public Convenience Chy Chimney PH Public House	Cis Citatern Pog Sta Pumping Station Dismit Riy Dismanted Railway PW Place of Worship El Gen Sta Electricity Generating Sweare Pos Sta Seware	Slice: A Site Area (Ha); 0.01
Co. Burgh Bdy. County Burgh Boundary (Scotland)	D Fn Drinking Fountain Pp Pump EIP Electricity Pillaror Post S.B. Signal Box or Bridge F.AP Fire Alarm Pillar S.S.S. Signal Postor Light	Station Station Electricity Point SB, SB Signal Box or Endge	Search builter (m). 100 Site Details
BP BS Boundary Postor Stone P.C.B Police Call Box B.R. Bridle Road P	FB FootBridge Spr Spring GP Guide Post Tk Tank or Track	El Sub Sta Electricity Sub Station S.P., SL Signal Post or Light FB Filter Bed Spr Spring	122, Drummond Street, LONDON, NW1 2HN
E.P. Electricity Pyton S.P. Signal Post P.B. FootBridge S.L. Sluice	H Hydrant or Hydraulic TCB Telephone Call Box LC Level Crossing	Fn/DFn Foundam/Dinking-Fn. Tk TankorTrack Gas.Gov. Gas.Vaive.Compound Tr Though	
#.r. roorraat 2.r. point G.P. Guide Postor Board 7.r. Treugh M.S. Mile Stone 7.r. Treugh	mer mannoie mannoie in in inough MP Mile Postor Mooring Post WrPt, WrT Water Point, Water Tap MS Mile Stone W Well	GP Guide Post WrPt, WrT WaterPoint, WaterTap MH Nanhole WaterDoint, WaterDoint, WaterTap	
M.P.M.R. MooringPostorRing Hr Well	NTL Normal Tidal Limit WorPp Wind Pump	MP,MS Mile Postor Mile Stone W Well	Area www.areinloudes.com A Landmark Information Group Service v47.0 07-May-2014 Page 1 of 19

Exercise total Exercise total Consist total Co
Electricity Ansat for order of a log of the second recent for th
Indicate feature Flow arrows Intertiet Main high Muntes Intertiet Muntes Main high Intertiet Muntes Muntes Intertiet Muntes Muntes Intertiet Muntes Muntes Intertiet Muntes Intertiet Muntes Interiet Muntes Intertiet

Document Control

Project title122 Drummond Street, London, NW1 2HNProject refJ14127								
Report prepared by	Matthew Elcog	Matthew Elcock/BEng FGS						
With input from	Martin Cooper	BEng CEng MICE FGS						
Report checked and approved for issue by	Steve Branch B	Sc MSc CGeol FGS FRGS N	MIEnvSc					
Issue No	Status	Date	Approved for Issue					
1	Final	15 May 2014	ON					

This report has been issued by the GEA office indicated below. Any enquiries regarding the report should be directed to the office indicated or to Steve Branch in our Herts office.

 \checkmark

Hertfordshire

tel 01727 824666

mail@gea-ltd.co.uk

Nottinghamshire

tel 01509 674888

888 midlan

midlands@gea-ltd.co.uk

Geotechnical & Environmental Associates Limited (GEA) disclaims any responsibility to the Client and others in respect of any matters outside the scope of this work. This report has been prepared with reasonable skill, care and diligence within the terms of the contract with the Client and taking account of the manpower, resources, investigation and testing devoted to it in agreement with the Client. This report is confidential to the Client and GEA accepts no responsibility of whatsoever nature to third parties to whom this report or any part thereof is made known, unless formally agreed beforehand. Any such party relies upon the report at their own risk. This report may provide advice based on an interpretation of legislation, guidance notes and codes of practice. GEA does not however provide legal advice and if specific legal advice is required a lawyer should be consulted.

i

© Geotechnical & Environmental Associates Limited 2014



Ref J14127 Issue No 1 15 May 201







	Geotechnical & Environmental Associates London Published 1895	Source map scale - 1:1,056 Four the 1:06 scale of Orthance Survey mapping was adopted from reland in The 1:166 scale of Orthance Survey mapping was adopted from reland in 1448 and was used to survey (wins with a population of over 4000, plus county hours of lesses to proplation, in in tonse counties mapped at the skirch scale in 141-55. The scale was the largest scale at which tondon was mapped by the Orthance Survey and a Skeletor in survey of the capital mapped by the Orthance Survey and a Skeletor in use of the skirch scale in 141-55. The scale was the largest scale at which tondon was understaten herwen risk and 1800. The majority of the 1:1056 scareys were there replaced by 1:500 surveys although almost all the remainder were revised at this scale, sometimes more than once before 1885. The type of append tomission of minor dealts such as seven access points and street abparent consiston of the map.	Please note: Due to the partial coverage of Historical Town Plans, it is possible that not all segments within an order will contain mapping. Only the segments that have Town Plan coverage will be generated. Map Name(s) and Date(s)	007_00_332 1007_00_333 1 1885 111056 111056 1 	Historical Town Plan - Segment A13	- A6A7	Order Details 55992834_1_1 Order Number: 55992834_1_1 Uustomer Ref: J14127 National Grid Reference: 529320, 182550 Slice: Area (Ha): 0.01 Search Buffer (m): 0	Site Details 122, Drummond Street, LONDON, NW1 2HN 22, Drummond Street, LONDON, NW1 2HN 22, Drummond Street, LONDON, NW1 2HN 244 9951 76: 0644 844 9951 76: 0646 844 9951 76: 0666 8561 9561 76: 0666 8561 9561 9561 9561 9561 9561 9561 9561 9
009625								
0014625								
002825								
000123								



	Geotechnical & Environmental Associates London Published 1911 - 1923	Source map scale - 1:1,056 Source map scale - 1:1,056 The 1:1056 scale of orbitance Survey mapping was adopted from reland in The 1:1056 scale of orbitance Survey mapping was adopted from reland in The 1:1056 scale of orbitance Survey mapping was mapped by the Orbitance Survey and a sketton survey of the capital scale in 19:41-55. The scale was the largest scale a withol London was mapped by the Orbitance Survey and a sketton survey of the capital stowing the more than stress state mans. Frompase and attudes, was undertaken heaveen 19:48 and 15:60. The majority of the 1:1056 surveys were taken replaced by 1:500 surveys; although almost all the remainder were atter replaced by 1:500 surveys; although almost all the remainder were revised at this scale; such as seven access points and street ignets may be as much a reflection of the generally earlier date of these plans, and the specification of the generally earlier date of these plans, and the specification of the generally earlier date of these plans, plasse note: Due to the partial coverage of Historical Town Plans, it is	possible that not all segments within an order will contain mapping. Only the segments that have Town Plan coverage will be generated. Map Name(s) and Date(s)	Historical Town Plan - Segment A13	- A6 A7 A6 A19 A10 A10	Order Details Order Number: 55992834_1_1 Customer Ref: J14127 National Grid Reference: 529320, 182550	Silce: A Site Area (Ha): 0.01 Search Buffer (m): 0 Site Details 122, Drummond Street, LONDON, NW1 2HN	A Landmark Tel: 084 84 985 Web: Www.environeck.co.uk A Landmark Information Group Service w47.0 07-May-2014 Page 3 ot 3
009625								top to the second secon
							un un un un	
								The second second
529400					E State			A A
002625								pava Para Para Para Para Para Para Para Par
								estimated 2013. All Fights Res
								put and Landmark Information Gr
521000							Theat	Crown copyri





CONTENTS

EXECUTIVE SUMMARY

Part	1: IN	VESTIGATION REPORT				
1.0	INTI	RODUCTION	1			
110	1.1	Proposed Development	1			
	1.2	Purpose of Work	1			
	1.3	Scope of Work	1			
	1.4	Limitations	2			
2.0	THE	ESITE	3			
	2.1	Site Description	3			
	2.2	Site History	3			
	2.3	Other Information	3			
	2.4	Geology and hydrogeology	4			
3.0	EXP	PLORATORY WORK	4			
4.0	GRC	DUND CONDITIONS	5			
	4.1	Made Ground	5			
	4.2	Lynch Hill Gravel Member	5			
	4.3	London Clay Formation	5			
	4.4	Groundwater	5			
	4.5	Existing Foundations	5			
Part	2: DF	ESIGN BASIS REPORT				
I UI U	-, DL					
5.0	INTI	RODUCTION	6			
6.0	GRC	DUND MODEL	6			
7.0	ADV	VISE AND RECOMMENDATIONS	6			
	7.1	Basement Construction	7			
	7.2	Spread Foundations	7			
	7.3	Shallow Excavations	8			

- Shallow Excavations 7.3
- 7.4 **Basement Floor Slab**
- 7.5 Hydrogeological Assessment
- 7.6 Contamination Risk Assessment

OUTSTANDING RISKS AND ISSUES 8.0

APPENDIX



8

8

8

9

EXECUTIVE SUMMARY

This executive summary contains an overview of the key findings and conclusions. No reliance should be placed on any part of the executive summary until the whole of the report has been read. Other sections of the report may contain information that puts into context the findings that are summarised in the executive summary.

BRIEF

This report describes the findings of a site investigation carried out by Geotechnical and Environmental Associates Limited (GEA), on the instructions of Michael Alexander Consulting Engineers, on behalf of Julia Pyper, with respect to the deepening of the vaults below the site by about 1.0 m. The purpose of the investigation has been to research the history of the site with respect to possible contaminative uses, to determine the ground conditions and hydrogeology, to assess the extent of any contamination and to provide information to assist with the design of the basement support and suitable foundations for the proposed development. The report also includes information required to comply with the London Borough of Camden (LBC) Planning Guidance CPG4.

SITE HISTORY

Greenwood's map of London, dated 1827, shows the site to have been developed with a building fronting onto Drummond Street to the south. The earliest Ordnance Survey (OS) map studied, dated 1873, shows the site to have been developed with the existing building and the surrounding area is in a similar layout as existing. Drummond Street is shown to the south of the site and the site appears to have been immediately surrounded by houses or shops. A saw mill is shown about 30 m south of the site, on the opposite side of Drummond Street. A smithy is shown about 20 m northeast of the site on the 1911 map. Sometime between the 1916 and 1953 map, buildings about 50 m northeast of the site were converted into a chemical works and engineering works which were labelled as warehouses from between 1959 to 1970. Fire Insurance Plans dating between 1889 and 1966 show the site to be occupied by a shop. The maps show the site to have remained unchanged from prior to 1873 until the present day.

GROUND CONDITIONS

The investigation has generally confirmed the expected ground conditions in that, below a limited thickness of made ground, Lynch Hill Gravel was encountered over the London Clay Formation, which extended to the maximum depth of the investigation, of 4.00 m. The made ground initially comprised greyish light brown slightly clayey gravelly sand with fragments of brick and extended to depths of between 0.25 m and 0.40 m and was underlain by a layer of paving stones, about 70 mm thick, below which blackish and greyish very dark brown sandy gravelly clay with fragments of coal, ash and bricks was encountered and extended to a depth of 0.70 m in Borehole No 1. The Lynch Hill Gravel comprised orange-brown sand and gravel and extended to a depth of 3.00 m. The London Clay initially comprised soft becoming firm brown silty sandy gravelly clay, which extended to a depth of 3.30 m, whereupon firm grey silty fissured clay with selenite crystals was encountered and extended to the maximum depth of the investigation, of 4.00 m. Groundwater was encountered at a depth of 2.50 m. Two trial pits excavated against the southern and eastern vault walls showed the brick walls to be directly bearing on made ground at depths of 260 mm and 600 mm respectively.

RECOMMENDATIONS

It is understood that the maximum excavation depth will be about 1.0 m, to accommodate a lower floor level in the vaults that will give an increased headroom. The investigation has indicated that groundwater will not be encountered in the 1.0 m deep excavation, and it should therefore be possible to simply underpin the existing foundations to bear in the Lynch Hill Gravel. Foundations bearing at this depth may be designed to apply a net allowable bearing pressure of 100 kN/m^2 .



Part 1: INVESTIGATION REPORT

This section of the report details the objectives of the investigation, the work that has been carried out to meet these objectives and the results of the investigation. Interpretation of the findings is presented in Part 2.

1.0 INTRODUCTION

Geotechnical and Environmental Associates (GEA) has been instructed by Michael Alexander Consulting Engineers, on behalf of Julia Pyper, to carry out a limited desk study, including hydrogeological assessment, and ground investigation at 122 Drummond Street, London, NW1 2HN.

1.1 **Proposed Development**

It is understood that it is proposed to deepen the existing vaults by a maximum of 1.0 m to provide further habitable space for the lower ground floor flat.

This report is specific to the proposed development and the advice herein should be reviewed once the development proposals are finalised.

1.2 **Purpose of Work**

The principal technical objectives of the work carried out were as follows:

- □ to check the history of the site with respect to previous contaminative uses;
- **u** to determine the ground conditions and their engineering properties;
- □ to investigate the configuration of existing foundations;
- to assess the possible impact of the proposed development on the local hydrogeology;
- □ to provide advice with respect to the design of suitable foundations and retaining walls; and
- □ to assess the risk that any such contamination may pose to the proposed development, its users or the wider environment.

1.3 Scope of Work

In order to meet the above objectives, a limited desk study was carried out followed by a ground investigation. The desk study comprised:

- □ a review of historical Ordnance Survey (OS) maps sourced from the Envirocheck database;
- a review of readily available geology maps; and
- a walkover survey of the site carried out in conjunction with the fieldwork.

In the light of this desk study an intrusive ground investigation was carried out which comprised, in summary, the following activities:

- a single borehole advanced by window sample techniques to a depth of 4.00 m;
- two hand excavated trial pit advanced to examine existing foundations; and
- □ provision of a report presenting and interpreting the above data, together with our advice and recommendations with respect to the proposed development.

The report includes a contaminated land assessment which has been undertaken in accordance with the methodology presented in Contaminated Land Report (CLR) 11¹ and involves identifying, making decisions on, and taking appropriate action to deal with, land contamination in a way that is consistent with government policies and legislation within the United Kingdom. The risk assessment is thus divided into three stages comprising Preliminary Risk Assessment, Generic Quantitative Risk Assessment, and Site-Specific Risk Assessment.

1.3.1 Basement Impact Assessment

The work carried out also includes information required for a Hydrogeological Assessment and Land Stability Assessment (also referred to as Slope Stability Assessment), which form part of the BIA procedure specified in the London Borough of Camden (LBC) Planning Guidance CPG4² and their Guidance for Subterranean Development³ prepared by Arup. The aim of this work is to provide information on the groundwater conditions specific to this site and land stability, in particular to assess whether the development will affect the stability of neighbouring properties and whether any identified impacts can be appropriately mitigated.

The BIA elements of the work have been carried out by Martin Cooper, a BEng in Civil Engineering, a chartered engineer (CEng) and member of the Institution of Civil Engineers (MICE), who has over 20 years specialist experience in ground engineering. The assessment has been made in conjunction with Steve Branch, a BSc in Engineering Geology and Geotechnics, MSc in Geotechnical Engineering, a chartered geologist (CGeol) and Fellow of the Geological Society (FGS) with 25 years' experience in geotechnical engineering, engineering geology and hydrogeology. Both assessors meet the Geotechnical Advisor criteria of the Site Investigation Steering Group and satisfy the qualification requirements of the Council guidance.

1.4 Limitations

The conclusions and recommendations made in this report are limited to those that can be made on the basis of the investigation. The results of the work should be viewed in the context of the range of data sources consulted and the number of locations where the ground was sampled. No liability can be accepted for information in other data sources or conditions not revealed by the sampling or testing. Any comments made on the basis of information obtained from the client or other third parties are given in good faith on the assumption that the information is accurate; no independent validation of such information has been made by GEA.

London Borough of Camden Planning Guidance CPG4 Basements and lightwells



¹ 2

Model Procedures for the Management of Land Contamination issued jointly by the Environment Agency and the Department for Environment, Food and Rural Affairs (DEFRA) Sept 2004

³ Ove Arup & Partners (2010) *Camden geological, hydrogeological and hydrological study. Guidance for Subterranean Development.* For London Borough of Camden November 2010

2.0 THE SITE

2.1 Site Description

The site is located approximately 100 m west of Euston London Underground and railway station and fronts onto Drummond Street to the south and is bordered by a similar three-storey terrace building to the east, a single storey building to the west and another building fronting onto Gower Street to the rear. The site may be additionally located by National Grid Reference 529348, 182570.

A walkover of the site was carried out by a geotechnical engineer from GEA at the time of the fieldwork, at which time access was only possible to the lightwell and vaults. The site is occupied by a four-storey building, including the lower ground floor level. A shop is present at ground floor level and the upper floors are presumably residential, as is the lower ground floor, which was unoccupied at the time of the investigation.

A lightwell is present in the front of the site and a staircase allows access to lower ground floor level. There are two vaults under the pavement, but it was only possible to access the eastern vault. The surrounding area is sensibly flat and the building occupies the entire site, which is devoid of vegetation.

2.2 Site History

The site history has been researched by reference to internet sources and historical Ordnance Survey (OS) maps obtained from the Envirocheck database.

Greenwood's map of London, dated 1827, shows the site to have been developed with a building fronting onto Drummond Street to the south.

The earliest Ordnance Survey (OS) map studied, dated 1873, shows the site to have been developed with the existing building and the surrounding area is in a similar layout as existing. Drummond Street is shown to the south of the site and the site appears to have been immediately surrounded by houses or shops. A saw mill is shown about 30 m south of the site, on the opposite side of Drummond Street. A disused burial ground is labelled about 105 m north of the site and Euston Station is also shown about 200 m to the northeast of the site.

The burial ground is labelled as St. James Gardens from 1895 and a smithy is shown about 20 m northeast of the site on the 1911 map. Sometime between the 1916 and 1953 maps, buildings about 50 m northeast of the site were converted into chemical works and engineering works which were labelled as warehouses from 1970 onward.

Fire Insurance Plans dating between 1889 and 1966 show the site to be occupied by a shop.

The maps show the site to have remained unchanged from prior to 1873 until the present day.

2.3 **Other Information**

Reference to records compiled by the Health Protection Agency (formerly the National Radiological Protection Board) indicates that the site falls within an area where less than 1% of homes are affected by radon emissions and therefore radon protective measures will not be necessary.



The Slope Angle Map (Fig 16) within the ARUP document indicates that the site and surrounding area does not have slopes greater than 7° .

Online mapping information suggests that London Underground tunnels are in close proximity of the site.

2.4 **Geology and Hydrogeology**

The British Geological Survey (BGS) map of the area indicates that the site is underlain by the Lynch Hill Gravel, which overlies the London Clay Formation.

The Lynch Hill Gravel is typically described as a sand and gravel but can contain layers of clay, silt and peat. The London Clay Formation is homogenous, slightly calcareous silty clay to very silty clay, with some beds of clayey silt grading to silty fine grained sand.

The Lynch Hill Gravel is classified by the Environment Agency as a Secondary 'A' Aquifer, which refers to permeable layers capable of supporting water supplies at a local rather than strategic scale, and in some cases forming an important source of base flow to rivers.

Under the same classification system the London Clay is designated as unproductive strata, which refers to deposits that have low permeability and negligible significance for water supply or river base flow.

Groundwater flow in the region of the site is likely to be controlled by contours, and thus generally toward the south.

3.0 EXPLORATORY WORK

In order to meet the objectives described in Section 1.2 as far as possible in view of the limited available access, a single window sample borehole was drilled in the lightwell to a depth of 4.00 m and two trial pits were excavated in the vaults to investigate the shallow foundations. The work was carried out under the supervision of a geotechnical engineer from GEA.

Disturbed samples were obtained from the borehole, but have not been tested to date.

The borehole and trial pit records are appended, together with a site plan indicating the exploratory positions.



4.0 GROUND CONDITIONS

The investigation has generally confirmed the expected ground conditions in that, below a limited thickness of made ground, the Lynch Hill Gravel was encountered over the London Clay, which extended to the maximum depth of the investigation.

4.1 Made Ground

The made ground initially comprised greyish light brown slightly clayey gravelly sand with fragments of bricks and extended to depths of between 0.25 m and 0.40 m which was underlain by a layer of paving slabs typically noted to be about 70 mm thick. Below the slabs blackish and greyish very dark brown sandy gravelly clay with fragments of coal, ash and bricks was encountered and extended to a depth of 0.70 m in Borehole No 1.

Apart from the presence of fragments of extraneous material noted above, no visual or olfactory evidence of contamination was observed during the fieldwork.

4.2 Lynch Hill Gravel Member

The Lynch Hill Gravel was only encountered in the borehole and comprised orange-brown fine to coarse sand and fine to coarse gravel and extended to a depth of 3.00 m.

These soils were observed to be free from obvious contamination.

4.3 London Clay Formation

The London Clay initially comprised a weathered zone of soft becoming firm brown silty sandy gravelly clay which extended to a depth of 3.30 m, whereupon firm grey silty fissured clay with selenite crystals was encountered and extended to the maximum depth of the investigation, of 4.00 m.

These soils were observed to be free from obvious contamination.

4.4 Groundwater

Groundwater was not encountered in the trial pits, but was indicated at a depth of 2.50 m in the sampling tubes.

The borehole was dipped upon completion and had collapsed to a depth of 3.60; water was measured at a depth of 3.48 m.

4.5 **Existing Foundations**

Trial Pit No 1, excavated on the southern vault elevation showed the brick wall to be directly bearing on made ground at a depth of 260 mm.

Trial Pit No 2, excavated adjacent to the eastern vault wall similarly showed the brick to be directly bearing on made ground, but at a greater depth of 600 mm.

The trial pit records are included in the Appendix.

