## JM PARTNERSHIP (SURVEYORS) LTD SITE INSPECTION SHEET

(Items man		quired to be actioned for c	ompliance with the Building	
_	sentative:- Shaun Go 2031766767		in Mob. No:- 07900784190	
SITE:-	TO PROVIDE A	DDITIONAL ACCOMMO	O SKYLIGHTS IN REAR GA DATION TO EXISTING SING ) AT 2 QUICKSWOOD, LOND	LE
REF. NO:- LON/14/14141		DATE:-24/7/2014	VISIT NO:- 1	

A commencement site visit was carried out unaccompanied view the progress of the works.

## The following observations were made:-

1. Request for visit to inspect a commencement of works to the basement.



- 2. 1 no underpinning bases seen which has now poured. Unable to determine depth of base as ground was covered over. Unable to determine ground condition. 75mm dry-packing seen above base in between base and existing foundation over. Please confirm depth and sub-strata.
- 3. Ground to be backfilled until further works continue.

