

33 BETTERTON STREET, LONDON WC2H 9BP.



① EXPOSURE OF THE FOUNDATION TO THE FRONT WALL - R.H. CORNER.

33 BETTERTON STREET, London WC2H 9BP.



② Exposure of the foundation to L.H. Wall - Near the Staircase.

33 - BETTERTON STREET, London WC2H 9BP.



③ EXPOSURE OF THE DRAIN TO REAR YARD.

33 BETTERTON STREET, LONDON WC2H 9BP.



④ NEW Lintel to the Basement Bathroom Door opening.