ST_3622_IMG_50 NTS 03/10/14 Existing Photographs - Front






KEY

- 1 Existing office building to be demolished as outlined in red2 B1 Office3 Residential

ST_3622_IMG_51 NTS Existing Photographs - Rear








1 Existing office building to be demolished as outlined in red
2 B1 - Office
3 Residential
4 3no 17m Black Locust trees to be removed

03/10/14

- 5 Courtyard
 6 Existing cycle storage + Plant to be removed









Stiff + Trevillion