



Photo 12 - Garage gates detail, St Albans Rd



Photo 13 - Looking down St Albans Rd pavement, 34 Brookfield Park to left




Photo 14 - Detail of existing concrete post



Photo 15 - Concrete post and panel wall between 34 Brookfield Park and 47 Kingswear Road



Photo 16 - Detail of concrete post and panel wall between 34 Brookfield Park and 47 Kingswear Road



Photo 17 - detail of join between post and gate, taken from within 34 Brookfield Park



Photo 18 - Existing compost bins, 34 Brookfield Park



Photo 20 - Existing garage forecourt concrete, looing to house






Photo 19 - Existing garage forecourt concrete, looing to garage



Photo 21 - Detail of existing concrete post bottom



Photo 22 - Detail of existing concrete post top