

27 Grove terrace – evidence of opening up and existing site photos

PHOTOGRAPH 1

Dividing wall between the 2no bedrooms on the 3rd floor



PHOTOGRAPH 2

Other properties on the terrace with 2no windows in the mansard roof



PHOTOGRAPH 3
Wall to 2nd floor landing – evidence of different material to opening

