



1. View to Existing Shower room on 2nd Floor



2. Existing Shower room on 2nd Floor



3. Existing Shower room detail



4. View to Existing Door to Bathroom on 2nd Floor Plus



5.& 6. Existing Bathroom on 2nd Floor Plus



7. View to Existing Door to Bedroom 2 on 2nd Floor Plus



8.& 9. Existing Bedroom 2 on 2nd Floor



TITLE:	Photos of Existing Interior			NO:	P002	REV:	P3
PROJECT:	37 Chalcot Crescent			DATE:	02 DEC 2014		
				PAPER:	A3		
				SCALE:	NTS		
				SANYA POLESCUK ARCHITECTS			
				8A BELSIZE COURT GARAGES LONDON NW3 5AJ			
				T: 020 7431 8580 e-mail: enquires@polescukarchitects.com			