

Nos. 6-7 Railey Mews, London, NW5.


Photographs of building structure



Front elevation (prior to commencement of works)



Internal walls (following partial brick collapse).



Plant growth and wet rot internally (prior to commencement)