

2013/2481/P

Information relating to the discharge of condition 4 – Bird/bat box types and locations

K

D

G


A

6

LEVEL 11 EAST




- 9. 80mm crescent hole for swifts
- 10. 80mm crescent hole for swifts
- 11. 80mm crescent hole for swifts
- 12. 70mm crescent hole for bats
- 13. 80mm crescent hole for swifts
- 14. 70mm crescent hole for bats
- 15. Area 1A on West facade to match locations indicated above 1A 2.5 stretchers from end



J

LEVEL 01



- 9. 80mm crescent hole for swifts
- 10. 80mm crescent hole for swifts
- 11. 80mm crescent hole for swifts
- 12. 70mm crescent hole for bats
- 13. 80mm crescent hole for swifts
- 14. 70mm crescent hole for bats
- 15. Area 1A on West facade to match locations indicated above 1A 2.5 stretchers from end

Building T5
SK 892
Bird/bat box locations



High level: Bat/Swift

Low level: Sparrows, Nuthatches, Pied flycatchers

Building T5

SK_P5

Condition 4

Bird and bat box types: Bird brick house - Laid into stretcher bond brickwork.
To be read in conjunction with SK_891+892