



Reference G = Group H = Hedge	Age & Species	Height (m)	Crown Ht (m)	Diameter (cm)	Crown Spread (m) N W E S	Scaled Tree Diagram (m)	Notes	Recommendations (Independent of any development proposals)		Vigour	Amenity Value
								Priority	Inspect Freq (yrs)	Physiological Condition	Life Expectancy (yrs)
										Structural Condition	Retention Category
T1	Semi-Mature Turkey Hazel Cotinus coggygria.	9	5	28	3.5 4 3		Position: Street tree. Form: Single stemmed and vertical with a well-formed crown. History: Occasional pruning wounds due to crown lifting (healing well). Defects: No defects observed. Other: Girdling root at base.	No action required.	3	Moderate	Moderate
										n/a	3
T2	Semi-Mature Hornbeam Carpinus betulus.	10	4	36	4.5 4.5 5		Position: Street tree. Form: Multi-stemmed at 2.5m with a well-formed crown. History: No evidence of significant pruning. Defects: No defects observed.	No action required.	3	Moderate	High
										n/a	3