



**Sunlight Analysis
Crogsland Road
12-Dec-14**

Available sunlight as a percentage of annual unobstructed total (1486.0 Hrs)

Window Ref	Room Ref	Existing %			Proposed %			% Loss of Summer	% Loss of Winter	% Loss of Total
		Summer	Winter	Total	Summer	Winter	Total			
11 CROGLAND ROAD										
Ground Floor										
W1/10		8	0	8	7	0	7	12.50%	0.00%	12.50%
First Floor										
W1/11		34	17	51	30	9	39	11.76%	47.06%	23.53%
W3/11		32	15	47	22	5	27	31.25%	66.67%	42.55%
Second Floor										
W1/12		36	18	54	34	10	44	5.56%	44.44%	18.52%
W3/12		32	16	48	23	6	29	28.13%	62.50%	39.58%
W4/12		39	26	65	23	7	30	41.03%	73.08%	53.85%
Third Floor										
W1/13		35	16	51	28	6	34	20.00%	62.50%	33.33%
W2/13		36	17	53	34	8	42	5.56%	52.94%	20.75%
Fourth Floor										
W1/14		35	18	53	35	7	42	0.00%	61.11%	20.75%
W2/14		34	16	50	34	11	45	0.00%	31.25%	10.00%
9 CROGLAND ROAD										
Ground Floor										
W2/10		30	10	40	28	7	35	6.67%	30.00%	12.50%
First Floor										
W2/11		33	18	51	32	12	44	3.03%	33.33%	13.73%
Second Floor										
W2/12		36	18	54	36	12	48	0.00%	33.33%	11.11%
Third Floor										
W3/13		17	2	19	17	2	19	0.00%	0.00%	0.00%
W4/13		34	12	46	34	10	44	0.00%	16.67%	4.35%
Fourth Floor										
W3/14		28	4	32	28	3	31	0.00%	25.00%	3.13%
W4/14		35	15	50	35	13	48	0.00%	13.33%	4.00%
141-156 DENTON ESTATE										
Ground Floor										
W1/30		57	29	86	52	22	74	8.77%	24.14%	13.95%
W2/30		35	16	51	20	9	29	42.86%	43.75%	43.14%
First Floor										
W1/31		57	29	86	53	23	76	7.02%	20.69%	11.63%
W2/31		35	16	51	22	9	31	37.14%	43.75%	39.22%
Second Floor										
W1/32		57	29	86	56	24	80	1.75%	17.24%	6.98%
W2/32		35	16	51	25	10	35	28.57%	37.50%	31.37%