


PICTURE OF EXISTING TREE '1'

PICTURE OF EXISTING TREE '1'

Note:

This tree is outside the boundary of our site and will not be touched during the works



EVIDENCE THAT TREE PROTECTION A IN PLACE



EVIDENCE THAT TREE PROTECTION A IN PLACE




BASE DETAIL



EVIDENCE THAT TREE PROTECTION A IN PLACE

TREE PROTECTION WORKS



EVIDENCE THAT TREE PROTECTION B IN PLACE



EVIDENCE THAT TREE PROTECTION B IN PLACE



EVIDENCE THAT TREE PROTECTION B IN PLACE

TREE PROTECTION WORKS