

Inspection Photo Sheet
Farndale House, West End Lane, London NW6 4QX



1. General View



2. General View



3. Buttress



4. Buttress

Inspection Photo Sheet
Farndale House, West End Lane, London NW6 4QX



5. Typical Crack



6. Typical Cracking



7. Illustration of Loss of Verticality



8. Illustration of Loss of Verticality

