

Elevation, arrow to the two windows to be replaced on third floor of 7 Willow Road



The two windows to be replaced, both in poor repair



View from the living room, rotten wood visible



View from the bedroom, rotten wood



Rotten sill



Window warped

