

Further Examples of Highly Visible Alterations in South Hampstead Conservation Area

This document has been produced to show a sample of the many alterations that have been made to highly visible parts of the South Hampstead Conservation Area, mainly additions of railings to enable original decorative balconies to be converted to outside usable space, railing installations at roof level, and other alterations to roof level such as dormer or conservatory installation. We believe that our proposal is less visible than these adaptations, and thus is consistent with previously established measures to minimize visual prominence. These 22 properties below are just a sample of alterations in the Conservation Area, if you were to make a comprehensive survey many more would be apparent.



Figure 1 - Extension to railings at 122 Greencroft Gardens as seen from 122 Greencroft



Figure 2- Second and third floor balcony railing extensions of 124 Greencroft Gardens as seen from 124 Greencroft Gardens



Figure 3 - Railings extension of 3rd floor balcony and adaptation from decorative to usable space of 126 Greencroft Gardens as seen from 126 Greencroft



Figure 4 - Roof level railings at 90A Priory Road as seen from Priory Road




Figure 5 - Roof level railings at 91 Priory Road as seen from 90 Priory Road



Figure 6 - Roof level railings at 91 Priory Road as seen from 90 Priory Road



Figure 7 - Conservatory addition to roof of 78 Compayne Gardens as seen from 99 Priory Road



Figure 8 - Conservatory roof addition to 99 Priory Road as seen from 78 Compayne Gardens



Figure 9 - Rooftop extension to 59 Compayne Gardens as seen from 68 Compayne



Figure 10 - Rooftop railings of 59 Compayne Gardens as seen from 64 Compayne



Figure 11 - Installation of railings on balconies of 64 & 62 Compayne Gardens as seen from 64 Compayne



Figure 12 - Rooftop railings on 58 Compayne Gardens as seen from 58 Compayne Gardens



Figure 13 - Dormer windows on 33 & 31 Compayne Gardens and railings of 33, as seen from 42 Compayne



Figure 14 - Installation of balcony and railings at 40 Compayne Gardens as seen from 40 Compayne



Figure 15 -Railings and balcony of 38 Compayne Gardens as seen from 38 Compayne



Figure 16 – Railings at 68 Fairhazel Gardens as seen from 25 Compayne Gardens



Figure 17 – Railings at 38 Canfield Gardens as seen from 63 Canfield



Figure 18 - 36 Railings at 36 Canfield Gardens as seen from 59 Canfield



Figure 19 - Railings at 16 Canfield Gardens as seen from 37 Canfield



Figure 20 - Railings at 14 Canfield Gardens as seen from 25 Canfield