

Segmental Pediment over single door_Reference Picture



Segmental Pediment over double door_Reference Picture




Broken Pediment over single door_Reference Picture

The content of this document is strictly CONFIDENTIAL. Any unauthorised copying, disclosure or distribution of the material and information in this document is strictly forbidden.

All measurements are to be checked and confirmed on site by the contractor.

All dimensions are in mm unless otherwise stated.

FOR INFORMATION ONLY



tom**è**f

132-134 Lots Road Unit 108 World's End Studios SW10 0RJ London

INTERIORDESION T +44 20 7349 7199

TB

10 Chester Terrace

Tre

Reference Pictures for Decorative Pediments

Date Location Drawn by	Job No	Originator	Scale 1:20 @ A3	Number	Revision 00
1.12.2015		Location	Drawn by	A3008	