



GALLERY 42 CEILING - CRACKS IN PLASTER

GALLERY 42 CEILING - LIGHT FITTINGS TO BE REMOVED










GALLERY 43-45 CEILING - SUBSTANTIAL DAMAGE TO PLASTER MOULDINGS







GALLERY 43-45 CEILING - GRILL IN CEILING TO BE REMOVED AND PLASTER FINISH RESTORED

Project THE WHITE WING -GALLERIES 42-45

Prepared For The Trustees of the British Museum

Project No: 15.33058.00




HOK Qube, 90 Whitfield Street London, W1T 4EZ, UK *t* +44 (0)20 7636 2006 f +44 (0)20 7636 1987

All reproduction & intellectual property rights reserved 2015 In Association with

Alan Baxter Ltd 75 Cowcross Street London, EC1M 6EL

TGA Consulting Engineers The Rivergreen Centre, Aykley Heads Durham, DH1 5TS

Baker Mallett Suite 1, Churchill Square, Kings Hill West Malling, Kent, ME19 4YU



Original drawing is A1. Do not scale contents of this drawing. Sheet Number: Revision:

Α

A203