



- NOTES:**
1. All structural engineering drawings are to be read in conjunction with the preliminary report and related supporting documents.
  2. The drawings are based on the information provided by the client, and the client is responsible for the accuracy of the information provided. The client is advised to verify the information provided by the client with the relevant authorities.
  3. Do not rely on this drawing in other reports or other drawings. This drawing is for the use of the client only. It is not to be used for any other purpose without the written consent of the engineer.
  4. All dimensions are in millimeters and levels in meters.

**LEGEND:**

	M. - Master Mason
	Major Work of Structural Repairs (to be shown in green)
	S2 - Surface Damage
	Surface Area of Structural Repairs (to be shown in green)
	S2 - Existing Crack 5mm wide (Extend over the surface)
	S2 - Crack 5mm wide (Extend over the surface)
	O/C - Crack 3mm wide (Extend over the surface)
	O/C - Crack 3mm wide (Extend over the surface)
	P/C - Precast Concrete (to be shown in green)
	Structural Repairs (to be shown in green)
	Joint between brick, stone or self-curing bedding of masonry wall



**REPORT**

Scale: 1:50 at A0

**JOHNSTON**  
Consulting Civil & Structural Engineers

93 Great Smith Street  
London EC1A 3BS  
T: 020 7353 1810  
www.johnston-engineers.co.uk

**ST. STEPHEN'S CHURCH**  
ROSSLYN HILL, NW3  
CHURCH EXTERNAL  
NORTH ELEVATION

Drawn: M. P. P. Date: 15/01/2011  
Project No./Drawing No.: 8529/1101