



GROUND FLOOR



Health And Safety Information

	Details	Initials	Date
Asbestos Survey			
Structural Check/Lifting & Handling			
Site Survey			
Access and Egress/Site Compound			
Hazards Identified			

Location Plan

N.T.S

General Notes

Crittall window replacements including cills and sub-frames

Flat roof areas separating extension to the rest of the building.

Rev.	Details of Revision	Date	Sign

Client:

UNIVERSITY COLLEGE LONDON

FAITHFUL

GOULD

CONSTRUCTIVE EXPERTISE

Euston Tower 286 Euston Road London NW1 3AT

Tel. +44(0)20 7121 2121

Fax. +44(0)20 7121 2020

Project:

UCL JOHN ADAMS HALL

15-23 ENDSLEIGH STREET

LONDON

WC1H 0DP

Ref:

5146364

Drawing No:

UCL_JAH_P03

Title:

PLANNING APPLICATION

GROUND FLOOR CRITTALL WINDOW LOCATION

Scale:	Drawn:	Checked:	Co-ord chk:
1:250	LF	RS	

Original Size:	Date:	Date:	Date:
A3	22/03/2016	23/03/2016	

Status:

PLANNING APPLICATION