Marcus Foster Arboricultural Design & Consultancy

BA (Hons) | NDArb | AATechcert (ArborA) | EGS.Dip

Arboricultural Note

Photographs showing northern and southern boundaries adjacent to and within close proximity of proposed basement footprint and

Date:

29th April 2016

Site:

26 Dartmouth Park Avenue London NW5 1JN

Prepared by:

Marcus Foster BA (Hons); NDipArb; AATech.Cert; EGS.Dip


Notes:

It can be confirmed that there are no trees within the neighbouring properties to either the north and south of the rear garden boundary of 26 Dartmouth Park Avenue, London, NW5 within close proximity of the proposed development. As shown from the photographs that have been taken - 26/04/16, there are no trees which will be affected by excavation works.

Marcus Foster Arboricultural Design & Consultancy Tel: + 44 (0) 7812 024 070 Email: <u>marcus@mfdesignconsultancy.com</u> <u>www.mfdesignconsultancy.com</u>

Photographs

<u>1. View looking directly south from area of proposed development:</u> <u>26 Dartmouth Park Avenue</u>



2. View looking directly south east from area of proposed development: 26 Dartmouth Park Avenue



3. View looking directly north from area of proposed development: 26 Dartmouth Park Avenue

