

37 and 39 Rudall Crescent

Report Related to Approval of Condition

Application- 2013/0824/P- Condition 6

Condition 6-

Prior to the commencement of any works on site, evidence in the form of a report and photographs demonstrating that tree protection measures have been implemented in accordance with the approved details within Arboricultural Report 221019-PD-11a, by Tim Moya Associates, dated October 2012, shall be submitted to and approved in writing by the Local Planning Authority.

Prior to the commencement of the work in relation to the approved application 2013/0824/P, tree protection has been installed according to the approved Arboricultural Report 221019-PD-11a, by Tim Moya Associates, dated October 2012.

Protective fencing has been installed to the rear gardens of 37 and 39 Rudall Crescent in line with the report and as the following photographs:



37 Rudall Crescent Rear Garden- Protective Fencing



39 Rudall Crescent Rear Garden- Protective Fencing



39 Rudall Crescent Rear Garden- Protective Fencing



39 Rudall Crescent Rear Garden- Protective Fencing