


211 Sumatra Road, London, NW6 1PF - Google Earth Historical Image - dated 09/09/1999, showing existing rear dormer window in situation.



211 Sumatra Road, London, NW6 1PF - Google Earth Historical Image - dated 01/01/2002, showing existing rear dormer window in situation.



211 Sumatra Road, London, NW6 1PF - Google Earth Historical Image - dated 01/01/2006, showing existing rear dormer window in situation.



Images of the rear of the neighbouring property at 209 Sumatra Road, London, NW6 1PF, showing existing full width rear dormer window in situation.





Aerial image of Sumatra Road, London, NW6 1PF, showing existing rear dormer windows in situation to various properties.

