

# Site Photographs - External



Image 1: Author SHH



Image 2: Author SHH



Image 3: Author SHH

## Existing external images:

- 1) Athlone House: view looking south at the northern facade. This facade has seen most of the extension work, with the former NHS chimney stack and two-storey corner extension still present.
- 2) Athlone House: view looking north showing many original features still present, including the octagonal chimneys behind the south copula tower.
- 3) Athlone House: South-eastern corner showing the carbuncle extension that is to be replaced.