

Site Photographs - Internal



Image 1: Author SHH



Image 2: Author SHH



Image 3: Author SHH

Existing internal images:

- 1) Entrance hall looking towards the main entrance. The style of the original ceiling is still intact and will be retained whilst where possible when the opening is created.
- 2) Dining hall showing the original ceiling. This important feature will be fully restored and returned to its rich timber appearance.
- 3) Staircase hall feature window to be restored.

Site Photographs - Internal



Image 1: Author SHH



Image 2: Author SHH



Image 3: Author SHH

Existing internal images:

- 1) Non-original wall partition built by the NHS on the first floor to be removed.
- 2) First floor windows looking over Heath. Condition of this room is typical through the house.
- 3) External face of inner courtyard window to be fully retained.

Local Context

conservation area
Hampstead Heath
community consultation
previous applications