

Photo 1 Trench by T3 Willow – no roots of any significance found.



RECEIVED
03 AUG 2009

Photo 2



**Roots in excess of 50mmØ found from
Lime T1.**

**New trench excavated along differing
location.**

