

**DESIGN & ACCESS STATEMENT : APPENDIX I - PHOTOGRAPHS OF EXTG  
BRICKWORK**






























These photographs show the variety of different types of brickwork used in the original construction below the main grade level. They also show the generally very poor quality of the original construction, and the different types of bonding used.

Because of the extent of the variation in brick types used, and the extensive areas of poor construction, it would be highly impractical to retain large sections of the brickwork above the areas that would need to be replaced.