




LEVEL MONITORING - RELATIVE SURVEY READINGS

Provider Details		Client Details			Risk Address	
Name:	MHN Ltd	Insurance Co.:	RSA	Occupier:	Mrs N Johnson	
		Client Name:	Crawford	Address:	16 Heath Hurst Road	
Date of Issue:	27/7/16	Technical Mgr:	McEwan G	Address:	Hampstead	
		Email:	[REDACTED]	Town:	London	
		Client Ref:	SU1503854	County:	NW3 2RX	
Monitoring Details		Address:	National Subsidence Unit	Post Code:		
Instruction Date:	29/10/15	Address:	4th Floor 30 St Pauls Square	Tel Home:		
First Reading Date:	09/11/2015	Town:	Birmingham	Tel Work:		
Maximum No Visits:	7	County:		Mobile:	[REDACTED]	
Anticipated Expiry Date:	Nov 2016	Post Code:	B3 1QZ	Other:		
Monitoring Int:	2 Monthly	Other Email:	[REDACTED]	Other:		

Row No.	Point Name	X Co-ordinate	Y Co-ordinate	1	2	3	4	5	6	7	8	9	10	11
1		0.00	0.00											
2	1: Datum	0.00	9.30	10.0000	10.0000	10.0000	10.0000	10.0000						
3		2.00	9.30											
4	2	2.00	12.40	9.8837	9.8841	9.8847	9.8844	9.8847						
5	3	2.00	16.50	9.8349	9.8412	9.8476	9.8482	9.8458						
6	4	5.90	16.50	9.8754	9.8835	9.8839	9.8848	9.8810						
7		5.90	0.00											
8														
9														
10														
11														
12														
13														
14														
15														
16														
17														
18														
19														
20														
21														
22														
23														
24														
25														
26														
27														
28														
29														
30														
31														
32														



- 26/07/2016
No new issues of concern were reported at the time of our appointment.
- It was not possible to install all sites within the same mortar course. Therefore initial readings cannot be interpreted as Distortion Data.
- Readings have been made relative to station 1 located on the rear wall of the main house. It has an assumed value of 10.0000m. If this is not acceptable, please advise if a Deep datum is required.
- Further readings to be taken in September 2016.

