

FIDUCIA INTERIORS

SCHEDULE OF PHOTOS



IMAGE 1: View towards 104-105 Saffron Hill




IMAGE 2: View towards 104-109 Saffron Hill on the edge of the flat roof showing part of the roof terrace below



IMAGE 3: View towards the rear of 16 – 18 Kirby Street.




IMAGE 4: View towards 104-105 Saffron Hill from the edge of the flat roof showing the flat roof below



IMAGE 5: View towards the rear of 16 – 18 Kirby Street and 106-109 Saffron Hill



IMAGE 6: View towards the rear of 16 – 18 Kirby Street and 106-109 Saffron Hill showing the floors above the 2nd floor.



IMAGE 7: View towards the rear of 16 – 18 Kirby Street and 106-109 Saffron Hill showing the 2nd floor windows and the sky lights situated on the flat roof.



IMAGE 8: View towards the rear of 16 – 18 Kirby Street and 106-109 Saffron Hill showing roof detail including sky lights.



IMAGE 9: Image showing the man safe system that is situated on the roof.



IMAGE 10: View towards 106-109 Saffron Hill showing the Roof Terrace below the 2nd floor of 16-18 Kirby Street.