



Greenwood Historic Map shows the southern side of Avenue Road being developed, with some building presents on both side of the road. The site at the current location of No.62 Avenue Road is shown as green field (Note: approximate location indicated on the map)



1939-1945

The LCC Bomb damage map shows the building in what appears to be its current footprint. Many of the buildings to the south side of Avenue Road, including the building at No.62, are noted to have suffered minor blast damage.



1894

Dark Red Seriously day doubtful if

Light Red

Blast damage, minor in natur Light Blue

Light Green

V1 flying bomb

Avenue Road has been fully extended up to Swiss Cottage and developed to both sides. The site at the current location of No.62 Avenue Road is occupied by a large building with a rectangular footprint.



1991

The OS map shows the existing building in its current configuration.

- This drawing is to be read in conjunction with all other relevant architects and engineers drawings and the specification.
- 2. This drawing shows extracts from historical maps from the dates shown



4. Bomb damage key


Colour Key General blast (for guidance only) damage - not structural Black Blast damage, minor in nature Purple Damaged beyond Light Blue Clearance Dark Red Seriously damaged; Light Green doubtful if repairable Light Red

Seriously damaged, but repairable

V1 flying bomb

V2 long

FOR INFORMATION ONLY



1635/100/005