

SAMPLE / MOCK-UP/ BENCHMARK APPROVAL FORM (select one only)										
Subcontracto Works Packa	or / Supplier: age: D502-21-CPT-	SA-073	Project: Centre Point							
Sample Ref Nitems / Faca	No: Restoration of H de	eritage	Date: 19/07/16							
Sample / Mock-Up/ Benchmark Description: Cleaning Sample to Level 1 cills										
Floor/ Location:	CPT - North West Elevation / Level 1 cill.									
Specification Reference:	Contractors recommendation									
Other:										



Submittal Notes: For comment / approval.								
 PAYE have cleaned the tower using HDL and doff machine, however to cills 1-2 the dirt is far more stubborn and a stronger chemical is recommended to clean these areas as these will be seen easily from ground level. Tensid Limestone Restorer. Purpose of Issue: (<i>To be completed by Originator- tick one box only</i>) Inclusion into Mock-Up only 								
Signed:	On behalf of:	ARCHITECT	Date:					
Status: A B C (circle one) Comment:								
Signed:	On behalf of:	СМТ	Date:					
Status: A B C (circle one) Comment:								
Signed:	On behalf of:	OTHER (please specify)	Date:					
Status: A B C (circle one) Comment:								
Signed:	On behalf of:	BMCE	Date:					
FINAL STATUS: A B C (circle one) Comment: C C C C								

The sample sticker is as follows:

BROOKFIELD MULTIPLEX CONSTRUCTION EUROPE Centre Point, London								
ACONEX SAMPLE No.								
SUBMITTED BY:								
DESCRIPTION:								
	Architect	CMT	BMCE	Other				
NAME:								
DATE:								
SIGN:								
STATUS A/B/C								