




Before

After


REVISIONS	
MM/DD/YY	REMARKS
1	
2	



Above: Close board gate with trellis
 Below: Bike storage, hidden by existing hedge when viewed from street



Above: New sawn stone steps, 50mm thick, bullnose edge. Treads deeper than existing
 Uplights on path and side lights in house wall.
 Below: Decorative grill over glass panels



REVISIONS	
MM/DD/YY	REMARKS
1	
2	